

1   **Q.     *Re: Tab 5.1 - 2013 Company Building Renovations***

2  
3       **Has Newfoundland Power confirmed that there is water ingress behind the brick at**  
4       **the Carbonear location? Please provide same.**

5  
6   **A.**     Newfoundland Power has confirmed that there is water ingress behind the brick at the  
7           Carbonear location. As seen in Appendix A – Figure 3, water can ingress in the atrium  
8           through the extensive cracking in the brick. Local employees report that dampness and  
9           an associated odor are evident at times on the interior side of the brick walls.