1 Q. [Accounts 355.1 and 355.2] – As it relates to certain statements made in Mr. 2 Wiedmayer's rebuttal testimony on pages 19 through 23 or in Appendix B pages 2 3 through 6, as it applies to Accounts 355.1 and 355.2 – Transmission Poles and 4 Fixtures, please provide a detailed narrative of what each of the other factors are 5 that have contributed to the trend of a shorter life for the more recent placement 6 bands referred to on page 5 of Appendix B. Further, provide all documents related 7 to each separate factor and specifically explain how each separate factor 8 contributed to the trend to a shorter life.

9 10

11

12

13 14 A. The other factors referred to on page 5 of Appendix B that have contributed to the trend of a shorter life for the more recent placement bands include line replacements, line relocations, and damage from high winds, snow and ice. These factors were specifically identified in the response to Request for Information CA-NP-084, Attachment A, page 13.

The Company has experienced a number of extreme weather events over the 1990 to 2009 period that have caused significant damage to transmission lines, particularly in eastern Newfoundland.