

1    Q.    Have either of Hydro's gas turbine plants had similar pressure relief line failures?

2

3

4    A.    Hydro's other gas turbine plants have not had similar pressure relief line failures.

5        Following the fire event on Hardwoods End B, the pressure relief lines were

6        replaced on Hardwoods End A and Stephenville End A and B.