

1 Q. Are the costs associated with the replacement engine included in the \$1,249,300
2 capital cost estimate for this project?

3

4

5 A. The costs associated with the replacement engine are not included in the
6 \$1,249,300 capital cost estimate for this project.