

1 Q. Following the 2011 refurbishment, did Hydro expect to get more than  
2 approximately 4 years of service from the overhauled engine before catastrophic  
3 failure of the combustion chambers?  
4

5

6

7 A. While the refurbishment was warranted for two years, Hydro typically has operated  
these engines for ten or more years after refurbishment, depending on usage.