

1 Q. What was the reason for the 2011 overhaul of the engine, and was the condition of
2 the combustion chambers addressed as part of that overhaul?

3

4

5 A. The engine overhaul was completed based on the recommendation of Stantec in
6 the *Condition Assessment and Life Cycle Cost Analysis Hardwoods and Stephenville*
7 *Gas Turbine Facilities* report. The condition of the combustion chambers was
8 addressed as part of the overhaul.