

1 Q. **Projects over \$50,000 but Less Than \$200,000**

2 Tab 6 Replace Station Service Breakers - Cat Arm:

3 Hydro outlines that the PLC system was installed in 1986 and is now obsolete. How
4 long has the system been obsolete?

5

6

7 A. Production of components for this PLC finished in 2001. Typically, suppliers support
8 this type of equipment for ten years after it is discontinued. Therefore, this PLC has
9 been obsolete since 2011.