

1 Q. **Project C-5: Replace Interior Coating of Surge Tank 3**

2 With reference to IC-NLH-16, did Hydro consider only refurbishing only localized
3 areas of coating breakdown followed by the application of a compatible coating
4 system thereto? If yes, why was this option not deemed appropriate by Hydro?

5

6

7 A. Please refer to Hydro's response to IC-NLH-016.