

1 Q. **Project C-5: Replace Interior Coating of Surge Tank 3**

2 With reference to IC-NLH-16, if known, what would be the cost savings of
3 refurbishing only localized areas of coating breakdown (followed by the application
4 of a compatible coating system) as opposed to the refurbishment of all interior
5 surfaces including surface preparation and coating of the surge tank and riser
6 interior?

7

8

9 A. Please refer to Hydro's response to IC-NLH-016.