

1 Q. **Project C-17: Replace ABB Exciter Unit 2 – Cat Arm**

2 At pages 3-4 of Hydro’s Report in relation to this Project, Hydro relates that Table 1
3 lists the quantities of “spare parts in inventory and remaining from those previously
4 removed from Unit 1 exciter”. Does Hydro have any other spare parts in inventory
5 beyond those previously removed from Unit 1 Exciter?

6

7

8 A. Hydro does not have any other spare parts beyond those in inventory and those in
9 the exciter removed from service in 2002. The available spare parts for the ABB
10 exciter is shown on page 4, Table 1 of the submitted report. There is, however, an
11 error in the table as the quantity in inventory for the Stabilizing Signal Adapter, ABB
12 Part No. UN0089a-P should be one rather than zero. The spare parts list was
13 confirmed by Kestrel Power Engineering during their assessment and is shown in
14 Appendix D of their report, which is located in Appendix B of the report submitted
15 for the proposal.

16

17 The BBC Type A 16030 exciter on Unit 2 at Cat Arm is the only one on the Hydro
18 system.