

1 Q. **Project C-37: Perform Wood Pole Line Management Project**

2 With reference to the “Justification” for the 2015 Wood Pole Management project
3 set out on page 5 of the Tab 15 report, identify the percentage of poles sampled
4 which did not meet the minimum preservative retention level, for each line
5 inspected in the Central region.

6
7
8 A. The 2002 inspection program in the Central region involved sampling on TL220, in
9 the Bay d’Espoir region. The results of this sampling are presented in the table
10 below:

11

Line	# Poles Sampled	# Poles Not Meeting Minimum Retention Level	% Poles Not Meeting Minimum Retention Level
TL220	13	9	69%