

1 Q. **Reference: Upgrade Powerhouse Roofing – Holyrood, Volume I, Tab 4**
 2 Has there been any major work or upgrades on the powerhouse roof for the past 10
 3 years? If so, please provide details.

4

5

6 A. All major work and upgrades, completed on the powerhouse roof since the year
 7 2000, are stated in Table 1: Major Work and Upgrades, located on page 5, Tab 5, of
 8 the report, Volume I, and is provided below.

9

10 **Table 1: Major Work and Upgrades**

Year	Major Work or Upgrade	Comments
2005	Miscellaneous repairs	Roof A
2005	1500 square feet of roof replaced	Roof G
2005	Roof Scanned, Miscellaneous Roof Repairs	Roof B
2005	Roof Scanned, Miscellaneous Roof Repairs	Roof B1
2005	Roof Scanned, Miscellaneous Roof Repairs	Roof C
2005	Miscellaneous Roof Repairs	Roof D
2005	Flashing repairs, re-application of coating and gravel	Roof J1
2005	Reinforcement of rubber flashing, re-application of coating and gravel	Roof G2
2004	Repair of minor deficiencies	Roof H
2004	Rubber flashing repairs	Roof G1
2004	Spot applications of penefelt and gravel	Roof G
2004	Flashing repairs, penefelt patching	Roof F1
2004	Roof patching	Roof J
2004	16 ft. 2 wet insulation replaced, rubber flashing repairs, penefelt patching	Roof I
2004	Flashing repairs, roof patching	Roof K
2004	Flashing repairs, roof patching	Roof L
2003	Area of wet insulation replaced	Roof F
2003	Re-application of coating	Roof F1

Year	Major Work or Upgrade	Comments
2002	1800 ft. 2 of roof replaced	Roof F1
2002	375 square feet of wet insulation replaced	Roof G
2002	3 Ply walkway membrane installed	Roof G1
2000	Flashing repairs, Re-application of coating	Roof C
2000	Stones removed, coating applied	Roof B
2000	Re-application of coating	Roof G
2000	Re-application of coating system	Roof E
2000	Re-application of coating	Roof F