

1 Q. Reference: Refurbish Generation Unit – Snook’s Arm, Volume I, Section D,

2 Page D-53

3 *“In 2002 Hydro inspected the components of the turbine and documented the*

4 *results in a report titled Snook’s Arm Turbine Inspection (see Appendix C).”*

5 Has Hydro completed any other inspection of the components of the Snook’s Arm

6 turbine since this 2002 inspection?

7

8

9 A. Hydro has not completed any other assessment of the Snook’s Arm turbine since

10 this 2002 inspection.