

1 Q. **C-59; Volume II, Tab 25: Construct Second Distribution Feeder – Nain**
2 Please explain what happened in 2011 to cause the significant increase in Net
3 Energy (MWh) as displayed in Figure 2: Nain System Load History 2009-2013.

4

5

6 A. The six percent increase in Net Energy (MWh) requirements in 2011 was primarily
7 the result of weather patterns as 2010 was significantly warmer than 2009 and
8 2011. As a result of the weather pattern, the load growth from 2009 to 2010 was
9 masked by the warmer 2010 weather.