1	Q.	Reference: Purchase 12MW of Diesel Generation (Revised), Page 1, Lines 8-15.
2		
3		"As part of these reviews and in light of recent events in the supply of electricity on
4		the system, Hydro has considered the following items in its provision of reliable
5		electricity supply:
6		1. There is a risk of a shortfall of capacity for customers on the Avalon
7		Peninsula due to customers forecasted needs on the Avalon;
8		2. There has been an increase in availability concerns regarding Hydro's
9		thermal generating units increasing the risk of a capacity shortfall; and
10		3. There is currently a material reduction in water available to Hydro for
11		hydraulic generation."
12		
13		Is the increase in availability concerns regarding Hydro's thermal generating units
14		identified in item 2 related to the boiler tube failures experienced in early 2016 at
15		the Holyrood Thermal Generating Station? If so, are the availability concerns
16		regarding Hydro's thermal generating units expected to be resolved by the boiler
17		repairs in the summer of 2016?
18		
19		
20	A.	The replacement of boiler reheat tubing this summer will address one concern, the
21		continued aging of in-service components and parts can result in increasing
22		likelihood of failure of other items. While Hydro is continuously inspecting and
23		monitoring all systems to mitigate the risk of failure of components or systems,
24		Hydro's increasing concern is a result of continuously increasing likelihood of age
25		failures in systems which affect the availability of the units. Therefore, the
26		availability concerns will not end, but be somewhat mitigated post additional
27		reheat tube replacements.