

1 Q. Reference: *Gas Generator Engine Refurbishments Hardwoods and Stephenville*,

2 Page 3, lines 15-20:

3

4 *“The engine was removed from the plant and replaced, on an interim basis, with a*  
5 *leased spare unit provided by Alba Power Ltd. The leased unit is of smaller*  
6 *generation capacity (19MW vs 25MW) than the one being replaced, but fit the*  
7 *installation berth and was readily available for the quickest in-service date during*  
8 *the winter period. The cost of the leased unit is \$4,000 per week plus \$42 for each*  
9 *hour of operation.”*

10

11 If the response to NP-NLH-001 above is yes, has Hydro continued to lease the  
12 replacement engine from Alba Power from the time when engine serial number  
13 202224 was returned to service in the fall of 2015 until February 8, 2016 when  
14 engine serial number 202225 failed?

15

16

17 A. Yes, Hydro continued to lease the replacement engine from Alba Power from the  
18 time engine 202224 was returned to service until the time engine serial number  
19 202205 failed.