

1 Q. **Volume II, Tab 7 – Rehabilitate Shoreline Protection, Cat Arm**

2 To what extent is this expenditure brought about by the failure of the 2005 work?

3

4

5 A. As a result of isolated failures along sections of the roadway embankment, Hydro
6 estimates that approximately 17% of the material placed in 2005 has been lost. The
7 proposed expenditure in this project is to address these isolated sections of the
8 2005 work.