

1 Q. **Project C-12: Rewind Rotor and Install Flux Probe Unit 3 - Holyrood**

2 Did Hydro consider rewinding the stator during the 2016 scheduled major
3 overhaul? If so, why did Hydro not consider the rewinding of the stator in 2016 a
4 viable option?

5

6

7 A. The AMEC Condition Assessment Report (Appendix C of the Board report for this
8 project contained in Tab 5 of Volume 2) states that there does not appear to be any
9 identifiable major issue to call for a stator rewind during the 2016 outage. It is
10 expected that the likelihood of a stator winding failure and forced outage in the
11 next five years is in the low to medium possibility range.

12

13 Option 1 of this report (rewind the rotor and carry out inspections on the stator in
14 2016) was selected by Hydro as the preferred option. This selection is also the
15 option recommended by FM Global (Hydro's insurance provider). The FM Global
16 Risk Report is included in Appendix A of the Board report.