

1 Q. In discussions with staff at the Holyrood facility on Aug. 19, 2011 a relevant report  
2 was identified. Please provide the report where Stantec carried out a review and  
3 condition assessment of the electrical switchgear for the facility.

4

5

6 A. Please see attached Exhibit 67. The report is the basis for ongoing capital work at  
7 the Holyrood facility, and its completion has been factored into the AMEC condition  
8 assessment.