

1 **Re Page B-38:**

2 Q. Is there a measured or measurable decrease in performance and efficiency
3 of the high pressure heater due to tube plugging being in excess of 10%?

4

5

6 A. Please see response to IC23-NLH.