

1 **Re Page B-158:**

2 Q. Provide maintenance records for the two units being replaced for the past  
3 two years.

4

5

6 A. Maintenance of these units is typically performed in-house and detailed  
7 maintenance records are not retained. Work orders are generated  
8 electronically and once the work is completed, the costs associated with the  
9 work and a very brief summary of the actual work performed is recorded  
10 against the work order.

11

12 Our maintenance records for the two units go back to 1999 and over that  
13 period the maintenance cost for each unit is:

14

15 Unit # 7646 - \$115,000

16 Unit # 7649 - \$ 62,000

17

18 Following is a summary of the maintenance costs for the two units for the  
19 past two years.

V7646			
G/L Date	Work Order	Amount	W.O. Description
10/23/2005	00006755	\$103.50	V7646
3/1/2005	00439827	\$9,732.00	VEH#7646,REPAIR/VARIOUS
3/1/2005	00441980	\$13,103.91	V7646,TRACKS,REPLACE
4/10/2005	00458562	\$414.00	V7646,MOUNTING PAD,REPLACE
8/14/2005	00472723	\$931.50	V7646,OIL LEAK,CLEAN OUT
11/6/2005	00482466	\$241.50	V7646 WHBTRANS SEMI ANNUAL PM
9/25/2005	00488008	\$138.00	V7646,GLASS,DOOR,REPLACE
11/23/2005	00493039	\$4,400.00	VEH#7646,WHEEL ASSEMBLY,REPLAC
11/6/2005	00494279	\$138.00	VEH#7646,WATER IN FUEL
11/6/2005	00494559	\$69.00	VEH#7646,TRACK LOOSE
1/15/2006	00500753	\$138.00	V7646,WINDOW,REPAIR
6/4/2006	00501333	\$621.00	V7646,WINDSHIELD,REPLACE
9/20/2006	00501335	\$1,732.57	V7646,BRAKE CALIPER,REPLACE
7/2/2006	00501337	\$241.50	V7646,CABLE WINCH,REPLACE
1/15/2006	00502584	\$5,770.53	*V7646,REAIR BROKEN SIDE AXLE
4/4/2006	00505947	\$2,854.00	*V7646,SEAL,LEAKY,REPAIR
2/12/2006	00507145	\$379.00	*V7646,SEATBELT,REPLACE
6/18/2006	00512979	\$1,138.50	V7646 WHBTRANS SEMI ANNUAL PM
6/27/2006	00533855	\$2,200.00	V7646,WHEEL ASSY,REPLACE
8/30/2006	00542904	\$1,231.02	V7646,CHECK FOR LEAKS
1/14/2007	00543065	\$483.00	V7646 WHBTRANS SEMI ANNUAL PM
5/7/2007	00567525	\$2,130.00	VEH7646,CAB REPAIR
6/3/2007	00574151	\$401.50	V7646 WHBTRANS SEMI ANNUAL PM
6/20/2007	00584532	\$4,075.92	V7646,SIDE AXLE,REPLACE
5/29/2007	00588973	\$977.04	VEH#7646,WHEEL ASSY,REPLACE
Two year total		\$53,644.99	

<b>Unit # 7649 *</b>			
<b>G/L Date</b>	<b>Work Order</b>	<b>Amount</b>	<b>W.O. Description</b>
4/22/2007	00006708	\$379.50	V7649
1/16/2005	00441757	\$140.00	V7649,CLUTCH,ADJUST
1/16/2005	00443072	\$175.00	V7649,MOUNTING PLATE,REPAIR
1/16/2005	00445223	\$70.00	V7649,BATTERY,REPLACE
3/27/2005	00451471	\$280.00	V7649 BIFTRANS1 SEMI ANNUAL PM
3/27/2005	00455848	\$994.00	V7649-SPROCKET SEAL LEAKING
1/15/2006	00482463	\$1,069.50	V7649 BIFTRANS1 SEMI ANNUAL PM
2/26/2006	00502155	\$483.00	V7649-REPAIR FLOOR
3/12/2006	00512976	\$69.00	V7649 BIFTRANS1 SEMI ANNUAL PM
10/8/2006	00543062	\$276.00	V7649 BIFTRANS1 SEMI ANNUAL PM
2/22/2007	00568082	\$914.64	V7649-FUMES IN CAB
1/28/2007	00570207	\$448.50	V7649,BRAKES,REPAIR
3/20/2007	00571297	\$119.46	VEH7649,ANTIFREEZE LEAKING
2/25/2007	00574148	\$448.50	V7649 BIFTRANS1 SEMI ANNUAL PM
4/8/2007	00579594	\$448.50	V7649-CHECK TRANS.
3/27/2007	00579690	\$471.09	V7649-GROUND WIRE
5/20/2007	00585668	\$73.00	V7649-DOOR GLASS
Two Year Total		\$6,859.69	* Unit is currently out of service for major repairs with an estimated cost of \$25,000.