Page 1 of 1

1 Re	: Page	B-50.	Replace	Unit 2 Ma	ain Steam	Stop	Valve 9	\$171.	.300
------	--------	-------	---------	-----------	-----------	------	---------	--------	------

Q. Please explain, including information on cost, why "The new valve was
purchased and delivered to the plant in 2006".

4 5

6

7

8

9

10

A. The valve was purchased at a cost of \$87,131.00. It was intended that the valve would be purchased and installed in 2006 but the delivery period of the valve was found to be so long that it could not be installed during the scheduled outage. The valve will be installed during the next convenient outage in 2008.