

1 **Re: Page B-56, Stack Breeching Study \$115,100**

2 Q. In each of the stacks when, and at what cost, were borosilicate tiles last
3 replaced?

4

5

6 A. The following are the costs incurred to replace borosilicate tiles:

	<u>2002</u>	<u>2003</u>	<u>2004</u>	<u>2005</u>	<u>2006</u>
Unit 1	\$60,000	\$20,000	\$10,000	\$20,000	\$250,000
Unit 2	10,000	150,000	10,000	220,000	20,000
Unit 3	30,000	30,000	80,000	20,000	10,000