

1 **Re: Page B-56, Stack Breeching Study \$115,100**

2 Q. Is there available an Engineering study of the condition of the stack
3 breeching? If so, please provide a copy?

4

5

6 A. There is no engineering study available. A visual inspection of the breeching
7 indicates that there is significant deterioration. A detailed inspection and
8 condition assessment is required to determine the condition of the breeching
9 and support structures and identify a repair strategy.