

1 **Re: Page B-73, Replace Disconnect Switches, \$367,600**

2 Q. How many of the remaining disconnects have experienced the problems
3 described in this project?

4

5

6 A. Of the approximately 110 disconnects in service on the system,
7 approximately 22 disconnects are experiencing similar problems. So far, the
8 age and location of these switches are such that the problems can be
9 corrected through repairs and parts replacements. For the disconnects at
10 Cow Head and Daniel's Harbour, the extent of corrosion, wear and age of the
11 disconnects are such that the problems can only be corrected by a complete
12 replacement of the disconnects.