

1 **Re: Page B-105, Replace Poles, \$700,200**

2 Q. In which year did regular maintenance inspections identify the 75 poles to be
3 replaced on the South Brook system and the 50 poles to be replaced on the
4 Bay d'Espoir system?

5

6

7 A. The year that the respective maintenance inspections were completed are as
8 follows:

9

10 • South Brook System – Inspections were carried-out over a four year
11 period from 2003 to 2006 inclusive.

12

13 • Bay d'Espoir System – Inspections were carried out in 2005.