

1 **Re: Page B-128, Replace Mufflers, \$479,200**

2 Q. Please provide a schedule showing all carbon steel exhausts that have been
3 replaced as result of these requirements, the dates of replacement, the cost
4 of replacement, and the scheduled replacement of any others at a future
5 date.

6
7
8 A. Hydro has not replaced carbon steel stacks as a result of an environmental
9 requirement, but has replaced existing carbon steel with stainless steel when
10 original equipment has deteriorated. When existing carbon steel stacks have
11 required replacement, they have been replaced with stainless steel to
12 prolong the life of exhaust systems and reduce exhaust system maintenance.