

1    Q.    **B-24, Replace Relay Panels Unit 3, 2011 – \$271,100, 2012 –\$553,600**

2            Please provide the most recent dates of inspections of the relay panels for Units 1  
3            and 2.

4

5

6    A.    There is no annual relay cabinet inspection performed on relay cabinets for Units 1,  
7            2 or 3, as this practice is not industry standard. The cabinets are opened as required  
8            for troubleshooting or relay upgrades, and are inspected at that time.