

1 Q. **Re: Holyrood (HTGS) Stack Breeching**

2 With reference to Hydro's response (d) to IC-NLH-7, what recommendations did the
3 maintenance service contractor make for 'some upgrades" to arrest or reduce the
4 pace of deterioration of the current liner? Were these recommendations recorded
5 other than by discussion? What would be the cost of implementing those
6 upgrades?

7

8

9 A. It is Hydro's understanding that the upgrades to which Alstom refer are contained
10 within the recommendations provided in that report. Hydro used these
11 recommendations as key considerations in its stack breeching proposals. Hydro
12 received no recommendations other than those included in the report attached as
13 Appendix B to the July 2011 submission.