

1 Q. **Re: Project B-7 Refurbishment of Marine Terminal**

2 At page B18 of Appendix B, Hatch states that a further detailed investigation of the
3 fenders existing condition is required to assess the required remedial work. Has this
4 further detailed investigation been conducted and a report prepared with respect
5 to the results of that investigation?

6

7

8 A. No, further detailed investigation of the fender condition has not been completed
9 to date. This detailed inspection is required to ensure that the full extent of the
10 required remedial work is completed under this project. The inspection will be
11 completed in 2012 to facilitate the detailed engineering design.