

1 Q. **Re: B-5, Rewind Generator Units 1 and 2, \$112,200 in 2012, \$1,107,600 in 2013,**
2 **and \$10,681,400 in future years**

3 In relation to the AMEC report at page E3, are the partial discharge readings
4 checked annually to detect excessive greasing and to identify whether the next
5 planned inspection should be brought forward as recommended by AMEC?

6

7

8 A. Yes, partial discharge readings are taken and checked annually, to monitor
9 insulation deterioration of the generator stator windings. Any significant increase in
10 partial discharge activity will be analysed, and major outage scheduling will be
11 modified accordingly.