

1 Q. **B-36, Perform Wood Pole Management Program, \$2,513,300**
 2 What was found to be the condition of the poles on line TL-240, Labrador, during
 3 the testing performed in 2010?

4
 5

6 A. The following table details the condition of the poles on line TL-240, Labrador,
 7 during the testing performed in 2010.

Pole Rating	No. of Poles	Percentage
1	0	0%
2	875	86%
3	124	12%
4	17	2%
5	4	0%

8 The pole rating criteria are:

Pole Condition	Ranking	Action
Good	1	No Immediate action required provided analysis supports the condition.
Fair	2	No Immediate Action Required but needs to be followed up periodically provided analysis supports the condition.
Poor	3	No Immediate Action Required but needs to be followed up within 5 years.
Severe	4	Requires Analysis and possible Mitigation within 2 years.
Hazardous	5	Safety Issue - Emergency