Page 1 of 1

1	Q.	Unit 1 Stack Breeching: Has Hydro been advised by any of its consultants, or does
2		Hydro have any other evidence, that the floor of Unit 1 will require replacement
3		within the study period of the CBA for the Alternatives considered in section 4.3 of
4		the July 2011 Hydro report?
5		
6		
7	A.	Yes, Hydro does have evidence that the floor of Unit 1 will require replacement
8		within the study period of the CBA for the Alternatives considered in section 4.3 of
9		the July 2011 Hydro report. Presently, some cracks and heaving exist as indicated by
10		pictures on page B28 of the report titled <i>Upgrade Unit 1 Stack Breeching</i> dated July
11		2011. After discussion regarding the service life remaining in the existing floor, the
12		boiler service contractor estimates the floor will need to be replaced around 2015.
13		Refer to part (a) of the response to IC-NLH-7.