

1 Q. Re: Account P07: Please provide the timing and magnitude of each inspection
2 program implemented in the past that impacted Account P07 – Pole - Wood.
3 Further, identify the timing, number and corresponding cost of poles retired as a
4 result of each such program.

5

6

7 A. There have been no inspection programs implemented in the past that impacted
8 account P07 – Pole – Wood since Hydro does not currently have an inspection
9 program for its distribution assets.