Q. Re: Account P07: Please provide a detailed explanation of the retirement at ages
14.5, and 16.5 years for Account P07 – Poles - Wood as set forth on page IV-147 of
Exhibit 1, including but not limited to a detailed description of what retired along
with corresponding dollars, the events that resulted in the need for retirement at
those ages, documents supporting the transaction, etc. Further, fully justify why
such events should be considered representative of future expectations for the
remaining plant.

A. Refer to CA-NLH-107 Attachment 1 for a detailed listing of the specific items that were retired at ages 14.5 and 16.5 years. Detailed reasons for retirements are not maintained in Hydro's asset records, however they are generally for replacement of plant as a result of the normal course of activity, as evidenced by the number of retirements in these years. As such, these retirement transactions should be included in the retirement rate analysis as they represent retirement activity that can be expected to reoccur in the future.

## Retirements at Ages 14.5 and 16.5 Years for Account P07 - Poles -Wood

New	Old			Install	Original Cost		to at 1.8 co 1 110 and 2010 real of 101 reconstruction	7.00	
Account	Account	Trans Type	Trns Year	Year	Amount	Age	Asset Description	Description	
P07	51500	Retirement	1996	1981	(13,238)	14.5	Adjust for Inventory Items Central	Distribution Upgrading	- Central
P07	51500	Retirement	1996	1981	(271,141)	14.5	Retire Distribution Assets from Northwestern	Distribution Upgrading	- Northwestern
P07	51500	Retirement	1996	1981	(11,975)	14.5	Retire Distribution Assets from Northern	Distribution Upgrading	- Northern
P07	51500	Retirement	1996	1981	(52,802)	14.5	Retire Distribution Assets from Northern	Distribution Upgrading	- Northern
P07	51500	Retirement	1996	1981	(1,308)	14.5	Retire 40' Poles from St. Anthony Substation	Distribution Upgrading	- Northern
P07	51500	Retirement	1996	1981	(22,068)	14.5	Retire Poles Sold to Newtel from Western		
P07	51500	Retirement	1996	1981	(2,920)	14.5	Retire Labour Costs on Transfers		
P07	51500	Retirement	1999	1984	(809)	14.5	45 FT. Wood Poles	Distribution Upgrading	- Central
P07	51500	Retirement	1999	1984	(1,138)	14.5	40 FT. Wood Poles	Distribution Upgrading	- Central
P07	51500	Retirement	1999	1984	(1,556)	14.5	35 FT. Wood Poles	Distribution Upgrading	- Central
P07	51500	Retirement	1999	1984	(2,006)	14.5	45 FT. Wood Poles	Distribution Upgrading	
P07	51500	Retirement	1999	1984	(2,845)	14.5	40 FT. Wood Poles	Distribution Upgrading	
P07	51500	Retirement	1999	1984	(3,012)	14.5	35 FT. Wood Poles	Distribution Upgrading	- Central
P07	51500	Retirement	1999	1984	(1,576)	14.5	40 FT. Wood Poles	Distribution Upgrading	
P07	51500	Retirement	1999	1984	(10,485)	14.5	40 FT. Wood Poles	Distribution Upgrading	
P07	51500	Retirement	1999	1984	(625)	14.5	40 FT. Wood Poles	Distribution Upgrading	
P07	51500	Retirement	2000	1985	(2,298)	14.5	30 FT. Wood Poles	Distribution Upgrading	- Central
P07	51500	Retirement	2001	1986	(534)	14.5	30 FT. Wood Poles	Distribution Upgrading	
P07	51500	Retirement	2001	1986	(2,176)	14.5	35 FT. Wood Poles	Distribution Upgrading	
P07	51500	Retirement	2001	1986			40 FT. Wood Poles	Distribution Upgrading	
P07	51500	Retirement	2001	1986	(4,829)	14.5	40 FT. Wood Poles	Distribution Upgrading	
P07	51500	Retirement	2001	1986	(534)	14.5	30 FT. Wood Poles	Distribution Upgrading	
P07	51500	Retirement	2001	1986	(1,890)	14.5	35 FT. Wood Poles	Distribution Upgrading	
P07	51500	Retirement	2001	1986			35 FT. Wood Poles	Distribution Upgrading	
P07	51500	Retirement	2001	1986	(687)	14.5	45 FT. Wood Poles	Distribution Upgrading	- Northern
P07	51500	Retirement	2001	1986	(783)	14.5	40 FT. Wood Poles	Pole Replacement - Sou	th Brook& King's Point
P07	51500	Retirement	2001	1986			40 FT. Wood Poles	Pole Replacement - Sou	•
P07	51500	Retirement	2001	1986	(832)	14.5	50 FT. Wood Poles	Pole Replacement - Sou	th Brook& King's Point
P07	51500	Retirement	2001	1986	(1,718)	14.5	35 FT. Wood Poles	Pole Replacement - Sou	th Brook& King's Point
P07	51500	Retirement	2001	1986	(1,174)	14.5	35 FT. Wood Poles	Distribution Pole Replac	cement - Bottom Waters
P07	51500	Retirement	2001	1986	(1,374)	14.5	45 FT. Wood Poles	Distribution Pole Replac	cement - Bottom Waters
P07	51500	Retirement	2001	1986	(3,314)	14.5	35 FT. Wood Poles	Distribution Pole Replac	cement - Bottom Waters
P07	51500	Retirement	2001	1986	(1,381)	14.5	30 FT. Wood Poles	Distribution Pole Replace	cement - Bottom Waters
P07	51500	Retirement	2001	1986	(21,493)	14.5	40 FT. Wood Poles		cement - Bottom Waters
P07	51500	Retirement	2002	1987			40 FT. Wood Poles		on-Replace Conductor/Poles - Burgeo
P07	51500	Retirement	2002	1987	(1,286)	14.5	45 FT. Wood Poles		on-Replace Conductor/Poles - Burgeo
P07	51500	Retirement	2003	1988	(8,467)	14.5	40 FT. Wood Poles	Replace Poles - Farewel	l Head Dist.System
P07	51500	Retirement	2003	1988	(704)	14.5	45 FT. Wood Poles	Replace Poles - Farewel	· · · · · · · · · · · · · · · · · · ·
P07	51500	Retirement	2005	1990			35 FT. Wood Poles	•	- Central Interconnected
P07	51500	Retirement	2005	1990	(3,677)	14.5	45 FT. Wood Poles		- Central Interconnected
P07	51500	Retirement	2005	1990	(775)	14.5	40 FT. Wood Poles		- Labrador Interconnect, Labrador City & Wabush
P07	51500	Retirement	2005	1990	` '		45 FT. Wood Poles		- Labrador Interconnect, Labrador City & Wabush
P07	51500	Retirement	2005	1990			45 FT. Wood Poles		- Labrador Interconnect, Labrador City & Wabush
P07	51500	Retirement	2005	1990			40 FT. Wood Poles		- Northern Interconnected
P07	51500	Retirement	2006	1991			35 FT. Wood Poles		vstem - Bear Cove Line 6
P07	51500	Retirement	2007	1992	` '		40 FT. Wood Poles		- Central Interconnected
P07	51500	Retirement	2008	1993	, ,		30 FT. Wood Poles		e Replacement Bay D'Espoir
					, -/			-,	• •

## Retirements at Ages 14.5 and 16.5 Years for Account P07 - Poles -Wood

New	Old			Install	Original Cost			
Account	Account	Trans Type	Trns Year	Year	Amount	Age	Asset Description	Description
P07	51500	Retirement	2008	1993	(659)	14.5	30 FT. Wood Poles	Distribution Upgrading - Central Diesel
P07	51500	Retirement	2008	1993	(4,414)	14.5	35 FT. Wood Poles	Reconfigure Feeders - Happy Valley Distribution System
P07	51500	Retirement	2008	1993	(835)	14.5	40 FT. Wood Poles	Distribution Upgrading - Labrador East Diesel
P07	51500	Retirement	2008	1993	(1,533)	14.5	35 FT. Wood Poles	Upgrade Distribution System - Mary's Harbour
P07	51500	Retirement	2008	1993	(612)	14.5	40 FT. Wood Poles	Upgrade Distribution System - St. Anthony Line 3
P07	51500	Retirement	2009	1994	(947)	14.5	50 FT. Wood Poles	Distribution Upgrading - Northern L'Anse au Loup
P07	51500	Retirement	2009	1994	(512)	14.5	35 FT. Wood Poles	Distribution Upgrading - Northern Interconnected
P07	51500	Retirement	2009	1994	(868)	14.5	35 FT. Wood Poles	Distribution Upgrading - Northern Interconnected
P07	51500	Retirement	2009	1994	(1,756)	14.5	40 FT. Wood Poles	Distribution Upgrading - Northern Interconnected
P07	51500	Retirement	2009	1994	. , ,		45 FT. Wood Poles	Distribution Upgrading - Northern Interconnected
P07	51500	Retirement	1998	1981	(101,649)	16.5	Adjustment for Inventory Items	
P07	51500	Retirement	1998	1981	(149,052)	16.5	Record Proceeds on Poles Sold to Newtel	
P07	51500	Retirement	1998	1981	(13,535)	16.5	Adjustment to Inventory	
P07	51500	Retirement	1999	1982			45 FT. Wood Poles	Distribution Upgrading - Central
P07	51500	Retirement	1999	1982	. , ,		35 FT. Wood Poles	Distribution Upgrading - Central
P07	51500	Retirement	1999	1982			30 FT. Wood Poles	Distribution Upgrading - Central
P07	51500	Retirement	1999	1982			50 FT. Wood Poles	Distribution Upgrading - Central
P07	51500	Retirement	1999	1982			35 FT. Wood Poles	Distribution Upgrading - Central
P07	51500	Retirement	2000	1983	. , ,		35 FT. Wood Poles	Distribution Upgrading - Labrador
P07	51500	Retirement	2000	1983	. , ,		30 FT. Wood Poles	Replace Poles - Fogo & Change Islands
P07	51500	Retirement	2001	1984	, ,		35 FT. Wood Poles	Distribution Upgrading - Central
P07	51500	Retirement	2001	1984			40 FT. Wood Poles	Distribution Upgrading - Central
P07	51500	Retirement	2001	1984			40 FT. Wood Poles	Distribution Upgrading - Northern
P07	51500	Retirement	2001	1984			35 FT. Wood Poles	Distribution Upgrading - Northern
P07	51500	Retirement	2001	1984			30 FT. Wood Poles	Distribution Upgrading - Northern
P07	51500	Retirement	2001	1984	. , ,		45 FT. Wood Poles	Distribution Upgrading - Northern
P07	51500	Retirement	2001	1984	. , ,		30 FT. Wood Poles	Distribution Upgrading - Northern
P07	51500	Retirement	2001	1984			40 FT. Wood Poles	Distribution Upgrading - Northern
P07	51500	Retirement	2001	1984			45 FT. Wood Poles	Distribution Upgrading - Northern
P07	51500	Retirement	2001	1984			30 FT. Wood Poles	Distribution Upgrading - Northern
P07 P07	51500	Retirement	2001	1984			35 FT. Wood Poles	Distribution Upgrading - Northern
	51500	Retirement	2001	1984	. , ,		40 FT. Wood Poles	Distribution Upgrading - Northern
P07 P07	51500	Retirement	2001	1984			30 FT. Wood Poles	Distribution Upgrading - Northern
	51500	Retirement	2001	1984			40 FT. Wood Poles	Distribution Upgrading - Northern
P07 P07	51500 51500	Retirement Retirement	2001 2001	1984 1984			30 FT. Wood Poles 30 FT. Wood Poles	Distribution Upgrading - Northern Distribution Upgrading - Northern
P07	51500	Retirement	2001	1984			40 FT. Wood Poles	Distribution Upgrading - Northern
P07	51500	Retirement	2001	1984	, ,		45 FT. Wood Poles	Pole Replacement - South Brook& King's Point
P07	51500	Retirement	2001	1985	, ,		40 FT. Wood Poles	Grandy Brook Distribution-Replace Conductor/Poles - Burgeo
P07	51500	Retirement	2002	1986			35 FT. Wood Poles	Distribution System Upgrade - Little Bay
P07	51500	Retirement	2004	1987			35 FT. Wood Poles	Distribution Upgrading - Northern
P07	51500	Retirement	2004	1987	, ,		35 FT. Wood Poles	Distribution Opgrading - Northern  Distribution Upgrading - Northern
P07	51500	Retirement	2004	1987			35 FT. Wood Poles	Distribution Upgrading - Northern
P07	51500	Retirement	2004	1987			30 FT. Wood Poles	Distribution Upgrading - Northern
P07	51500	Retirement	2004	1987	, ,		30 FT. Wood Poles	Distribution Upgrading - Labrador
P07	51500	Retirement	2004	1987			35 FT. Wood Poles	Distribution Opgrading - Labrador  Distribution Upgrading - Northern L'Anse au Loup
P07	51500	Retirement	2004	1988			40 FT. Wood Poles	Distribution Upgrading - Labrador East Diesel
P07	51500	Retirement	2005	1988			40 FT. Wood Poles	Distribution Upgrading - Labrador East Diesel
P07	51500	Retirement	2005	1989	` '		35 FT. Wood Poles	Distribution Upgrading - Central Interconnected
107	31300	ACTION CHICK	2000	1303	(033)	10.5	33 1 1. ¥¥000 I OIC3	Distribution Oppruning Central Interconnected

## Retirements at Ages 14.5 and 16.5 Years for Account P07 - Poles -Wood

New	Old			Install	Original Cost			
Account	Account	Trans Type	Trns Year	Year	Amount	Age	Asset Description	Description
P07	51500	Retirement	2006	1989	(1,391)	16.5	40 FT. Wood Poles	Distribution Upgrading - Central Interconnected
P07	51500	Retirement	2006	1989	(368)	16.5	30 FT. Wood Poles	Distribution Upgrading - Central Interconnected
P07	51500	Retirement	2007	1990	(2,242)	16.5	50 FT. Wood Poles	Distribution Upgrading - Northern Interconnected
P07	51500	Retirement	2007	1990	(1,140)	16.5	45 FT. Wood Poles	Distribution Upgrading - Northern Interconnected
P07	51500	Retirement	2007	1990	(641)	16.5	30 FT. Wood Poles	Upgrade Distribution System - St. Anthony Line 1 and Line 2
P07	51500	Retirement	2007	1990	(6,721)	16.5	40 FT. Wood Poles	Upgrade Distribution System - Rocky Harbour Line 1 and Line 2
P07	51500	Retirement	2008	1991	(1,082)	16.5	35 FT. Wood Poles	Distribution Upgrading - Central Interconnected
P07	51500	Retirement	2009	1992	(613)	16.5	40 FT. Wood Poles	Distribution Upgrading - Northern L'Anse au Loup
P07	51500	Retirement	2009	1992	(2,849)	16.5	35 FT. Wood Poles	Distribution Upgrading - Northern L'Anse au Loup