

1    Q.    Since the time T5 has not been in service, why have there been no assessments  
2           made as to the extent of work that needs to be carried out, the time it will take,  
3           how much it will cost and whether T5 is in fact repairable?  
4

5

6    A.    There have been no assessments made since Transformer T5 has been out of  
7           service because there was no evidence that the transformer may be unfit to return  
8           to service until the moisture results of the oil sample obtained in April 2014 were  
9           obtained. There were no known problems with T5 when it was taken out of service  
10          in January 2007 and Hydro's records indicate that no problems were identified  
11          during the preventative maintenance performed on it in September 2006.  
12          Transformer T5 is an installed spare transformer and is only placed into service  
13          when the need arises.