

1 Q. On page 8 of the report it is noted that in the spring of 2014 there was an attempt
2 to place T5 back in service but due to unacceptable moisture levels this was not
3 possible. When and why was this transformer taken out of service?
4

5
6 A. Transformer T5 was removed from service in January 2007 when it was no longer
7 needed. Transformer T5 is an installed spare transformer and is only placed into
8 service when the need arises. It was removed from service in January 2007 when
9 Wabush transformer T4, which had been out of service, was put back in service.