

1 Q. Upon investigation of the unacceptable moisture levels in the transformer oil of T5,
2 what was the determination with regard to the cause of the high moisture levels in
3 the transformers insulation?

4

5

6 A. Please refer to Hydro's response to CA-NLH-5.