Page 1 of 1

| 1 | Q. | On page 25 of the Upgrade Transmission Line Corridor Report it is noted that for |
|----|----|--|
| 2 | | analysis purposes TL203 is considered to be rebuilt. Does Hydro intend to rebuild |
| 3 | | TL203 and what are the implications for system operations if this rebuild is not |
| 4 | | done? |
| 5 | | |
| 6 | | |
| 7 | A. | Rebuild of TL203 as part of the alternatives considered during the analysis did not |
| 8 | | provide a technically viable alternative to construction of the Bay d'Espoir to |
| 9 | | Western Avalon 230 kV transmission line. With the new Bay d'Espoir to Western |
| 10 | | Avalon line constructed, there are no overloads to TL203 for single contingency line |
| 11 | | outages in the study period as summarized in Section 6.2.3. |
| 12 | | |
| 13 | | Transmission line TL203 is currently part of Hydro's Wood Pole Management |
| 14 | | Program and the reconstruction of the line is beyond Hydro's planning horizon. |
| | | |