

1 Q. **Upgrade Excitation Systems Units 1 and 2 (C-22; Tab 9 of Volume 2)**

2 On page 3 of the Report at Tab 9 it states that the ABB Unitrol P exciter was
3 installed on Unit 1 in 2000 and on Unit 2 in 1999 and that these were installed as
4 replacements for the originals installed in 1971. When these replacements were
5 purchased what were their expected useful lives?

6

7

8 A. The expected useful life of the control section was 15 years. The power sections
9 would be expected to have a life of 25 years.