

1 Q. **Tab D, 2014 Capital Projects \$200,000 and over but less than \$500,000:**

2 **Explanations – Inspect Fuel Storage Tanks, p. D-114**

3 At p. D-121, API Standard 653 states that routine in-service inspections of the  
4 exterior of a fuel storage tank should not exceed one month. Does Hydro plan to  
5 implement this one month in-service inspections on all fuel storage tanks?

6

7

8 A. No, Hydro already performs regular in-service inspections that satisfy this  
9 requirement.