

1 Q. **Tab E, 2014 Capital Projects \$50,000 and over but less than \$200,000:**

2 **Explanations – Construct Storage Facility, p. E-139**

3 Does Hydro possess any reports from its staff in Postville that would indicate that
4 the current configuration is hindering their ability to conduct day to day
5 maintenance work at the facility or is creating any other difficulties?
6

7

8

8 A. The following is an excerpt from an email from the Electrical/Mechanical
9 Supervisor for the Transmission and Rural Operations Labrador region on
10 September 12, 2013:

11 *The existing plant configuration gives very little room to do any significant*
12 *maintenance. For example, we have a major overhaul coming in the next 4-6*
13 *weeks. When this job begins, the plant will be totally covered in parts on the*
14 *floor from one end to the over (sic) with no room to work. Even if you look a*
15 *slightly less significant job, such as replace a cylinder pack or cylinder head.*
16 *You still would create a risky work environment full of trip hazards,*
17 *increasing a likely hood of injury. If you remove the oil drums, consumable*
18 *cabinets, some of the tooling, storage bins for maintenance, etc... it would*
19 *make a great difference.*