

1 Q. **Project C-20, Complete Condition Assessment Phase 2 – Holyrood**

2 On page 9 of the report filed at Volume II, Tab 8, Hydro advises that the focus of
3 this project will be on Unit 3 high energy piping, Unit 3 boiler locations and the Unit
4 2 generator. Inspection and refurbishment of Units 1 and 3 generators are
5 addressed under the regular overhaul schedule in Hydro's capital program; only the
6 Unit 2 generator is included in the scope of the 2014 program. Explain why the Unit
7 2 generator is not included in the regular overhaul schedule, particularly given that
8 Project C-18 relates to the major overhaul of Unit 2 turbine and generator.

9
10

11 A. The condition assessment work related to Unit 2 generator is not included in the
12 regular overhaul schedule because the inspection and testing work associated with
13 the condition assessment is more in depth than what normally would take place
14 under a regular major overhaul. For instance, an overhaul would not include
15 electrical testing which is included in the scope of the condition assessment.