

1 **B-100 Radio Replacement, \$225,600**

2 Q. Provide a maintenance record for the years 2001 to 2006F of the radio
3 providing service between Burnt Dam and the Bay d'Espoir Hydro
4 Generating Plant.

5

6

7 A. The maintenance record for the Burnt Dam radio for the years in question is
8 shown below.

Date	Problem	Resolution
Jan. 2003	Phone not working	Replaced ringer, decoder, faulty phone, and re-align radios.
Feb. 2003	VHF Multiplexer defective	Repair company notified Hydro that the multiplexer is non-repairable.
Jun. 2003	VHF radio dead	Replaced DC Converter and fuse.
Oct. 2003	Phone not working	Relocated radios at far end.
Sep. 2004	Noise & static on phone	Replaced VHF Radio chassis.
Dec. 2004	Unable to make calls	No fault found.
Sep. 2005	No dial tone	Reconfigured routers.
Nov. 2005	Noise; no ringing on incoming calls	No fault found.