## 1 B-37 Install Disconnect Switch, \$94,300

Q. Provide a listing of the outages that have occurred on TL220 downstream of
Conne River over the period 2001 to 2006.

4 5

6 A. The following table contains a listing of the outages on TL220 downstream of Conne River for the period 2001 to present.

Date	Time	Cause
2001 Feb 13	10:23 hrs	Salt Contamination
2001 Sept 28	13:40 hrs	Lightning
2001 Nov 11	18:41 hrs	Lightning
2002 Sept 13	21:59 hrs	Lightning
2002 Sept 13	22:14 hrs	Lightning
2003 Dec 8	03:30 hrs	High Winds
2003 Dec 8	06:19 hrs	High Winds
2003 Dec 8	07:20 hrs	High Winds
2003 Dec 8	07:35	High Winds
2006 Aug 22	09:04 hrs	Lightning