

1 Q. With reference to IC-NLH-017, if the 100 MW Combustion Turbine will be  
2 susceptible to corrosion or other wear and adverse conditions due to its close  
3 proximity to a coastal climate and coastal conditions, what inspection and  
4 maintenance regime has Hydro identified that can be put in place to detect such  
5 problems in a timely and reliable manner?  
6  
7

8 A. Hydro will be developing an inspection and maintenance program for the new plant  
9 in consultation with the supplier and manufacturer. It will address the needs of the  
10 new plant with consideration to any special requirements due to its coastal  
11 location. At this time that exercise has not been completed. In addition, it is Hydro's  
12 intention to register with the manufacturer of the plant to receive notification of  
13 any inspection or maintenance items that may be issued in the future.