

1 Q. The January 2014 outages showed that in addition to the Holyrood issues, system  
2 disruptions occurred due to issues with the other power supply equipment  
3 [Sunnyside and Western Avalon transformers, Sunnyside Bus protection failure].  
4 Please explain how reliability risks relating to such other power supply equipment  
5 issues are addressed in Hydro's report, and the potential for such other reliability  
6 risks to once again aggravate IIS disruptions.

7

8

9 A. As detailed in Section 5 of the Energy Supply Risk Assessment (ESRA) Report, Hydro  
10 has made significant investment in infrastructure, including other power supply  
11 equipment, in recent years to improve reliability for customers and will continue to  
12 do so into the future. In this way, Hydro continues to address reliability risks  
13 relating to other power supply equipment issues.

14

15 Studies and assessments of the availability of such power supply equipment are  
16 conducted as part of Hydro's Asset Management practises, and remediation efforts,  
17 if required, would be included in Hydro's Annual Work plan.