

1 Q. Table 4 [page 18] of the ESRA Report assumes all three Holyrood units were de-  
2 rated based on Hydro's Asset Management team recommendations. What is the  
3 Hydro's expectation of any future de-ratings of these units prior to 2021?  
4

5

6

7 A. Based upon boiler tube data obtained in 2015, the completion of 2016 boiler tube  
8 replacement, and reduced rates of corrosion due to the use of low sulfur fuel,  
9 Hydro does not expect further de-rating of Holyrood units will be required prior to  
10 2021.

11

12 If future boiler tube inspections and tube thickness analysis reveal corrosion rate  
13 trends that could impact the reliability of the boiler tubes then additional deratings  
may be required.