

1 Q. Please provide the numbers of subtransmission and distribution wood poles on the
2 system. How many subtransmission and distribution poles have been replaced over
3 the last 5 years?
4

5
6 A. Hydro has approximately 46,790 distribution wood poles in the system. Over the
7 last five years, approximately 2,850 have been replaced.
8

9 Hydro does not have any subtransmission lines on the Island Interconnected
10 System.