

1 Q. Reference: Gas Turbine Failure Analysis - Final Report, January 11, 2017. Please
2 confirm if Hydro's oil condition monitoring and management programs were
3 followed for the Stephenville gas turbine for the period between its last overhaul in
4 October 2014 to its failure on March 26, 2016. If the oil condition monitoring and
5 management programs were not followed, please explain why.

6

7

8 A. Hydro did follow the oil condition monitoring and management program in place at
9 the time for engine 202204 during the period October 25, 2014 to March 26, 2016.
10 Please also refer to Hydro's response to PUB-NLH-643.